



City of New Orleans
 Department of Public Works
 Lakeview City Park
 Proposed Drainage Improvements
 New Orleans, Louisiana

LOG OF BORING AND TEST RESULTS

Boring: B-1

Project No: 24192
 Date: 06/09/2020
 Latitude: 30.01924°
 Longitude: 90.09720°

Elevation: -1.7
 Datum: NAVD88
 Water Depth: See Text
 Total Depth: 10.0 ft

Scale in Feet	PP	SPT	S P L R	Symbol	Visual Classification	USC	Sample Number	Depth in Feet	Water Content %	Density		Shear Tests			Atterberg Limits			Other Tests
										Dry pcf	Wet pcf	Type	φ	C psf	LL	PL	PI	
0					Brown clayey sand w/silty sand & trace of roots	SC	1A	0	19									
					Brown silty sand w/clay pockets, trace of roots, & shell fragments	SM	1B	1	17									
					Gray silty clay w/trace of fine sand	CL	1C	2	19									
					Gray clay w/few silty sand pockets	CH	1D	3	44									
							1E	4	33					97	26	71		
5					Gray fine sand w/shell fragments & trace of silt	SP	2A	5	23									
					w/silt & shell fragments		2B	6	23									
					Greenish-gray clay w/fine sand pockets, decayed wood, & organic matter	CH	2C	7	48									
					Gray organic clay w/wood & trace of humus pockets	OH	2D	8	160									
					Gray peat w/wood & trace of silty sand	Pt	2E	9	192									
10																		

EUSTIS GINT LIBRARY062019.GLB EE STANDARD BORING LOG 24192.GPJ 6/23/21

NOTES: