



City of New Orleans
 Department of Public Works
 Lakeview City Park
 Proposed Drainage Improvements
 New Orleans, Louisiana

LOG OF BORING AND TEST RESULTS

Boring: B-3

Project No: 24192
 Date: 06/08/2020
 Latitude: 30.01823°
 Longitude: 90.09445°

Elevation: -3.9
 Datum: NAVD88
 Water Depth: See Text
 Total Depth: 10.0 ft

Scale in Feet	PP	SPT	S P L R	Symbol	Visual Classification	USC	Sample Number	Depth in Feet	Water Content %	Density		Shear Tests			Atterberg Limits			Other Tests
										Dry pcf	Wet pcf	Type	φ	C psf	LL	PL	PI	
0					Brown & gray clay w/vegetation & trace of clay pockets	CH	1A	0	28									
					Dark gray silty clay w/silt pockets, roots, & shell fragments	CL	1B	1	41									
					Gray & brown clay w/organic matter & decayed wood	CH	1C	2	97									
					Gray organic clay w/decayed wood	OH	1D	3	137									
					No recovery		NS	4										
5					Gray & dark gray clay w/decayed wood	CH	2A	5	118									
					Dark gray organic silt	OL	2B	6	153									
					Dark gray & gray clayey sandy silt w/trace of organic matter & wood	ML	2C	7	39									
					Gray silty clay w/organic matter, roots, & trace of clay pockets	CL	2D	8	95									
10					w/organic matter & roots		2E	9	62									#200 = 52.4%

EUSTIS GINT LIBRARY062019.GLB EE STANDARD BORING LOG 24192.GPJ 6/23/21

NOTES: