

City of New Orleans Department of Public Works Lakeview City Park Proposed Drainage Improvements New Orleans, Louisiana

LOG OF BORING AND TEST RESULTS

Boring: B-12

Project No: 24192 Date: 02/03/2021 Latitude: 29.99564° Longitude: -90.09957° Elevation: -2.9 Datum: NAVD88 Water Depth: See Text Total Depth: 10.0 ft

	Scale in	РР	SPT	S P L R	Symbol		USC	Sample Number	Depth in Feet	Water Content %	Density		Shear Tests		At	terberg	Limits	Other Tests
	Feet										Dry pcf	Wet pcf	Туре 🖣	C psf	LL	LL PL PI	other rests	
	0					Brown clay w/sand pockets, roots, & gravel	СН											
				W				1A	0	33								
	_				<u>/////</u>	Brown fine sand w/clay pockets	SP	-										
				Ŵ	•••••			1B	1	13								
								10		15								
	-	•				Green clay w/sand pockets & organic matter	СН											
								1C	2	59								
JG 24192.GPJ 6/24/21	-	1.00				Gray clay w/trace of concretions	СН	-										
						Gray cray wy trace of concretions		15	2	74								
								1D	3	71								
	-					Brown clay w/concretions & organic matter	СН	1										
				W		matter		1E	4	57								
	5 –			W														
STANDARD BORING LOG	-					w/concretions												
ORIN				W				2A	5	54								
RD E	-			WW		w/concretions & organic matter												
₫ND₽						matter		2B	6	55								
EE ST.	-			WW														
				Ŵ		Brown fine sand w/clay	SP											
19.G					•••••			2C	7	19								-#200 = 9.6%
EUSTIS GINT LIBRARY062019.GLB	_				••••	Brown sand	SP	1										
RAN				WW				2D	8	20								
T LIBI	_			000														
GIN						w/trace of silt												
ISTIS					•••••			2E	9	21								-#200 = 1.3%
Щ	- 10			Ø	• • •													

NOTES: