



City of New Orleans
 Department of Public Works
 Lakeview City Park
 Proposed Drainage Improvements
 New Orleans, Louisiana

LOG OF BORING AND TEST RESULTS

Boring: B-15

Project No: 24192
 Date: 02/04/2021
 Latitude: 29.99273°
 Longitude: -90.09974°

Elevation: -5.2
 Datum: NAVD88
 Water Depth: See Text
 Total Depth: 10.0 ft

| Scale in Feet | PP | SPT | S P L R Symbol | Visual Classification | USC | Sample Number | Depth in Feet | Water Content % | Density | | Shear Tests | | | Atterberg Limits | | | Other Tests | | |
|---------------|----|-----|-------------------|---|-----|---------------|---------------|-----------------|---------|---------|-------------|---|-------|------------------|----|----|-------------|--|--|
| | | | | | | | | | Dry pcf | Wet pcf | Type | φ | C psf | LL | PL | PI | | | |
| 0 | | | | Gray & tan clay w/trace of roots, silt pockets, shells, & brick fragments | CH | 1A | 0 | 40 | | | | | | | | | | | |
| | | | | w/trace of silt, organic matter, & shell fragments | | 1B | 1 | 48 | | | | | | | | | | | |
| | | | | w/trace of organic matter pockets | | 1C | 2 | 51 | | | | | | | | | | | |
| | | | | | | 1D | 3 | 52 | | | | | | | | | | | |
| 1.00 | | | | Brown clay w/wood & concretions | CH | 1E | 4 | 42 | | | | | | | | | | | |
| | | | | w/wood | | 2A | 5 | 51 | | | | | | | | | | | |
| 5 | | | | Gray clay w/wood | CH | 2B | 6 | 61 | | | | | | | | | | | |
| | | | | | | 2C | 7 | 76 | | | | | | | | | | | |
| | | | | Dark gray organic clay w/clay lenses, wood, & concretions | OH | 2D | 8 | 141 | | | | | | | | | | | |
| | | | | w/wood, roots, humus pockets, & trace of gray clay | | 2E | 9 | 149 | | | | | | | | | | | |
| 10 | | | | | | | | | | | | | | | | | | | |

EUSTIS GINT LIBRARY062019.GLB EE STANDARD BORING LOG 24192.GPJ 6/23/21

NOTES: