



City of New Orleans
 Department of Public Works
 Lakeview City Park
 Proposed Drainage Improvements
 New Orleans, Louisiana

LOG OF BORING AND TEST RESULTS

Boring: PS-7

Project No: 24192
 Date: 02/03/2021
 Latitude: 30.00544°
 Longitude: -90.09609°

Water Depth: See Text
 Total Depth: 6.0 ft

Scale in Feet	PP	SPT	S P L R	Symbol	Visual Classification	USC	Sample Number	Depth in Feet	Water Content %	Density		Shear Tests			Atterberg Limits			Other Tests
										Dry pcf	Wet pcf	Type	φ	C psf	LL	PL	PI	
0					1' Water	Water	NS	0										
0.50					Brown organic clay w/many roots & vegetation, & sand	OH	B-1	1	171									
0.50					Brown & black humus w/roots & trace of shell fragments	Pt	B-3	2	360									
0.50					Dark gray & brown organic clay w/organic matter, trace of wood & shell fragments	OH	B-4	4	305									
0.50					w/roots, decayed wood, humus pockets, & trace of shell fragments		B-5	5	309									

EUSTIS GINT LIBRARY062019.GLB EE STANDARD BORING LOG 24192.GPJ 6/23/21

NOTES: All PS Borings were sampled using a hand piston sampler.