

# BORING LOG

**BORING NO.:** C-8  
**PROJECT:** LakeView Street Reconstructions  
**PROJECT LOCATION:** Lakeview LA  
**BORING LOCATION:** N553356.85 E3670763.95  
**DATE DRILLED:** 02/08/2013  
**WATER LEVEL:** Not Encountered  
**GEOL/ENGR:** SE/SA

**PROJECT NO.:** APS-1211-G043  
**METHOD:** AUGER/WET ROTARY  
**BORING ELEVATION:** Not Surveyed  
**DATE COMPLETED:** 02/08/2013  
**WATER LEVEL DATE:** 02/08/2013  
**DRILLER:** VG

DEPTH (FEET)	SAMPLE	Standard Penetration (Blows/Ft.) or Penetrometer (TSF)	Qu (TSF)	Moisture Content (%)	Dry Unit Weight (PCF)	LL	PI	Symbol	MATERIAL CLASSIFICATION
								[Concrete Symbol]	5.5 Inches of Concrete
	5			11				[Sand Symbol]	Loose Poorly Graded Sand (SP) - Fill Material
			0.45	242	23	226	123	[Clay Symbol]	Soft Black Organic Clay (OH)
5				47		49	17	[Silt Symbol]	Black Silt (ML) with Organics
10									
15									
20									

**COMMENTS:**

- Rock Core
- Split Spoon
- Shelby Tube

**Argonne Boulevard**  
 APS Design and Testing, LLC