

# BORING LOG

**BORING NO.:** A-1

**PROJECT:** Lakeview Street Reconstructions

**PROJECT LOCATION:** LakeView LA

**BORING LOCATION:** N546478.99 E3670838.78

**DATE DRILLED:** 02/06/2013

**WATER LEVEL:** Not Encountered

**GEOL/ENGR:** SE/SA

**PROJECT NO.:** APS-1211-G043

**METHOD:** AUGER

**BORING ELEVATION:** Not Surveyed

**DATE COMPLETED:** 02/06/2013

**WATER LEVEL DATE:**

**DRILLER:** CM

DEPTH (FEET)	SAMPLE	Standard Penetration (Blows/Ft.) or Penetrometer (TSF)	Moisture Content (%)	LL	PI	Symbol	MATERIAL CLASSIFICATION
							3 Inches of Asphalt
							13 Inches of Base Material
							Gray Fat Clay (CH) with traces of Organics
		30		154	106		
5							Dense Gray Poorly Graded Sand (SP) Passing #200 Sieve @ 2'-4' 2.3%
		35	7				
							-Very Dense
		51	15				
10							
15							
20							

**COMMENTS:**

- Rock Core
- Shelby Tube
- Split Spoon

## Orleans Avenue

APS Design and Testing, LLC