






# BORING LOG

**BORING NO.:** POA-7  
**PROJECT:** Plum Orchard Street Rehabilitation  
**PROJECT LOCATION:** New Orleans LA  
**BORING LOCATION:** N554662.65 E3699275.5  
**DATE DRILLED:** 01/26/2013  
**WATER LEVEL:** Not Encountered  
**GEOL/ENGR:** SE/SA

**PROJECT NO.:** ASP-1304-G016  
**METHOD:** AUGER  
**BORING ELEVATION:** Not Surveyed  
**DATE COMPLETED:** 01/26/2013  
**WATER LEVEL DATE:** 01/26/2013  
**DRILLER:** VG

DEPTH (FEET)	SAMPLE	Qu (TSF)	Moisture Content (%)	Dry Unit Weight (PCF)	LL	PI	Symbol	MATERIAL CLASSIFICATION
0 - 2								2 Inches of Asphalt
2 - 8								8 Inches of Base Material
8 - 10			58		103	61		Gray Fat Clay (CH) with Organics
10 - 12		0.47	32	89	53	28		-Soft
12 - 20			86					

**COMMENTS:**

 Rock Core       Shelby Tube

**Prentiss Avenue**

APS Design and Testing, LLC