

BORING LOG

BORING NO.: POA-2
PROJECT: Plum Orchard Street Rehabilitation
PROJECT LOCATION: New Orleans LA
BORING LOCATION: N554586.6 E3702911.68
DATE DRILLED: 01/27/2013
WATER LEVEL: Not Encountered
GEOL/ENGR: SE/SA

PROJECT NO.: ASP-1304-G016
METHOD: AUGER
BORING ELEVATION: Not Surveyed
DATE COMPLETED: 01/27/2013
WATER LEVEL DATE: 01/27/2013
DRILLER: VG

DEPTH (FEET)	SAMPLE	Qu (TSF)	Moisture Content (%)	Dry Unit Weight (PCF)	LL	PI	Symbol	MATERIAL CLASSIFICATION
								2 Inches of Asphalt
								7 Inches of Base Material
			39		64	18		Gray Organic Silt (OH) with clay Percentage of Organics = 2.22
5		0.38	67	64	91	49		-Soft; Percentage of Organics = 2.41
			80					
10								
15								
20								

COMMENTS:

 Rock Core  Shelby Tube

Dreux Avenue

APS Design and Testing, LLC