

BORING LOG

BORING NO.: POA-5

PROJECT: Plum Orchard Street Rehabilitation

PROJECT LOCATION: New Orleans LA

BORING LOCATION: N555604.3 E3704677.44

DATE DRILLED: 01/26/2013

WATER LEVEL: Not Encountered

GEOL/ENGR: SE/SA

PROJECT NO.: ASP-1304-G016

METHOD: AUGER

BORING ELEVATION: Not Surveyed

DATE COMPLETED: 01/26/2013

WATER LEVEL DATE: 01/26/2013

DRILLER: VG

DEPTH (FEET)	SAMPLE	Qu (TSF)	Moisture Content (%)	Dry Unit Weight (PCF)	LL	PI	Symbol	MATERIAL CLASSIFICATION
0	[Shelby Tube]						[Cross-hatch]	2 Inches of Asphalt
							[Diagonal lines]	6 Inches of Base Material
							[Diagonal lines]	Gray Fat Clay (CH) with Organics
5	[Shelby Tube]	0.19	86	64	128	80	[Diagonal lines]	Gray Fat Clay (CH) with Organics
			60	29	90	51	[Vertical lines]	Very Soft Gray Elastic Silt (MH) with Organics
10	[Shelby Tube]							
15	[Shelby Tube]							
20	[Shelby Tube]							

COMMENTS:

[Vertical lines] Rock Core

[Shaded box] Shelby Tube

Hammond Street

APS Design and Testing, LLC