



City of New Orleans
 Pavement Investigation
 Dillard Neighborhood
 Orleans Parish, Louisiana
 Project No: 22243

LOG OF BORING AND TEST RESULTS

B-5

EUSTIS ENGINEERING

Date: 08/28/2013

Latitude: 30.00128
 Longitude: -90.06190

Water Depth: See Text
 Total Depth: 5.0 ft

Scale in Feet	PP	SPT	S P L R	Symbol	Visual Classification	USC	Sample Number	Depth in Feet	Water Content Percent	Density		Shear Tests			Atterberg Limits			Other Tests
										Dry	Wet	Type	ϕ	C	LL	PL	PI	
0					6" Asphalt		NS	0										
0.75		13	X		Medium stiff brown silty clay w/gravel, shell fragments, & trace of brick fragments	CL	1	0.5	12									
					Stiff gray & tan clay w/silt pockets & trace of decayed wood	CH	2	2	27					52	16	36		
1.25					Soft gray & tan clay w/silt pockets & trace of decayed wood	CH	3	4	33									
5																		
10																		
15																		
20																		
25																		

NOTES: No coring required.

EUSTIS GINT LIBRARY\04102013.GLB EE STANDARD BORING LOG 22243.GPJ EE STANDARD DATATEMPLATE.GDT 12/2/13