



City of New Orleans  
 St. Bernard Neighborhood, Public Works Damage and  
 Sewerage & Water Board Repairs  
 Orleans Parish, Louisiana  
 Project No: 22242

# LOG OF BORING AND TEST RESULTS

**B-1**

EUSTIS ENGINEERING

Date: 08/15/2013

Latitude: 29.99937  
 Longitude: 90.07507

Water Depth: See Text  
 Total Depth: 5.0 ft

Scale in Feet	PP	SPT	S P L R Symbol	Visual Classification	USC	Sample Number	Depth in Feet	Water Content Percent	Density		Shear Tests			Atterberg Limits			Other Tests	
									Dry	Wet	Type	$\phi$	C	LL	PL	PI		
0				6" Asphalt														
		13		Soft brown sandy clay w/gravel & shell fragments (base course fill)	CL	1	0.5	10										
				Medium stiff gray & tan clay w/silt pockets	CH	2	3	39	78	108	UC	--	517					
				Stiff brown & gray clay w/silt pockets & trace of decayed wood	CH	3	4	45										
5																		
10																		

NOTES:

EUSTIS GINT LIBRARY\04102013.GLB EE STANDARD BORING LOG - 22242.GPJ EE STANDARD DATATEMPLATE.GDT 9/30/13