



City of New Orleans
 St. Bernard Neighborhood, Public Works Damage and
 Sewerage & Water Board Repairs
 Orleans Parish, Louisiana
 Project No: 22242

LOG OF BORING AND TEST RESULTS

B-3

EUSTIS ENGINEERING

Date: 08/27/2013

Latitude: 29.99345
 Longitude: 90.08258

Water Depth: See Text
 Total Depth: 5.0 ft

Scale in Feet	PP	SPT	S P L R Symbol	Visual Classification	USC	Sample Number	Depth in Feet	Water Content Percent	Density		Shear Tests			Atterberg Limits			Other Tests	
									Dry	Wet	Type	φ	C	LL	PL	PI		
0				6" Asphalt														
		33		Crushed asphalt w/trace of silty clay (base course fill)	GP	1	0	9										
		10				2	2	16										
	0.25			Very soft gray clay w/trace of silt pockets, trace of decayed wood, trace of roots, & trace of brick fragments	CH	3	4	92	48	93	UC	-	223					
5																		
10																		

EUSTIS GINT LIBRARY04102013.GLB EE STANDARD BORING LOG 22242.GPJ EE STANDARD DATATEMPLATE.GDT 9/30/13

NOTES: