



City of New Orleans  
 St. Bernard Neighborhood, Public Works Damage and  
 Sewerage & Water Board Repairs  
 Orleans Parish, Louisiana  
 Project No: 22242

# LOG OF BORING AND TEST RESULTS

**B-4**

EUSTIS ENGINEERING

Date: 08/15/2013

Latitude: 29.99573  
 Longitude: 90.07930

Water Depth: See Text  
 Total Depth: 5.0 ft

Scale in Feet	PP	SPT	S P L R	Symbol	Visual Classification	USC	Sample Number	Depth in Feet	Water Content Percent	Density		Shear Tests			Atterberg Limits			Other Tests	
										Dry	Wet	Type	$\phi$	C	LL	PL	PI		
0					3" Asphalt														
					5" Concrete														
					Soft gray clay w/silt pockets, trace of shell fragments, & sandy silt pockets (base course fill)	CH	1	1	55	67	104	UC	--	464	103	24	79		
							2	2	52										
					Soft gray clay	CH	3	3											
							4	4	83										
5																			
10																			

NOTES:

EUSTIS GINT LIBRARY04102013.GLB EE STANDARD BORING LOG 22242.GPJ EE STANDARD DATATEMPLATE.GDT 9/30/13