



City of New Orleans
St. Bernard Neighborhood, Public Works Damage and
Sewerage & Water Board Repairs
Orleans Parish, Louisiana
Project No: 22242

LOG OF BORING AND TEST RESULTS

B-5

EUSTIS ENGINEERING

Date: 08/16/2013

Latitude: 29.99355
Longitude: 90.07460

Water Depth: See Text
Total Depth: 5.0 ft

Scale in Feet	PP	SPT	SPLR	Symbol	Visual Classification	USC	Sample Number	Depth in Feet	Water Content Percent	Density		Shear Tests			Atterberg Limits			Other Tests
										Dry	Wet	Type	ϕ	C	LL	PL	PI	
0					3" Concrete													
		2			Soft gray clay w/fine sand pockets, shell fragments, & gravel (base course fill)	CH												
					Soft gray & tan clay w/silty sand pockets & lenses, & trace of shell fragments	CH	1	0.5	39									
							2	3	38	82	113	UC	--	360				
					Medium stiff gray & tan clay w/silty sand pockets	CH	3	4	42						73	19	54	
5																		
10																		

NOTES: