BORING LOG

BORING NO.: POC-7

Split Spoon

PROJECT: Plum Orchard Street Rehabilitation **PROJECT LOCATION:** New Orleans LA

BORING LOCATION: N555359.94 E3705118.98

DATE DRILLED: 01/27/2013 WATER LEVEL: Not Encoutered GEOL/ENGR: SE/SA

PROJECT NO.: ASP-1304-G016

METHOD: AUGER

BORING ELEVATION: Not Surveyed **DATE COMPLETED:** 01/27/2013

WATER LEVEL DATE: 01/27/2013

DRILLER: VG

GEOL/ENGR: SE/SA				1	DRILLER: VG
DEPTH (FEET)	SAMPLE	Standard Penetration (Blows/Ft.) or Penetrometer (TSF)	Moisture Content (%)	Symbol	MATERIAL CLASSIFICATION
				D A A	7 Inches of Concrete
		6	7		Loose Brown Poorly Graded Sand (SP) with traces of silt
		7	12		-Loose; Passing #200 Sieve @ 2'-4' is 4.0%
_ 5 -		7	18		-Loose; traces of Silt
	_				
_ 10 -					
	_				
- 15 -					
_ 20 -					
COMMENTS:					

Eastview Drive

APS Design and Testing, LLC