

# BORING LOG

**BORING NO.:** POC-10

**PROJECT:** Plum Orchard Street Rehabilitation

**PROJECT LOCATION:** New Orleans LA

**BORING LOCATION:** N555563.22 E3704273.51

**DATE DRILLED:** 01/13/2013

**WATER LEVEL:** Not Encountered

**GEOL/ENGR:** SE/SA

**PROJECT NO.:** ASP-1304-G016

**METHOD:** AUGER

**BORING ELEVATION:** Not Surveyed

**DATE COMPLETED:** 01/13/2013

**WATER LEVEL DATE:** 01/13/2013

**DRILLER:** VG

DEPTH (FEET)	SAMPLE	Standard Penetration (Blows/Ft.) or Penetrometer (TSF)	Moisture Content (%)	Symbol	MATERIAL CLASSIFICATION
	[Rock Core Symbol]				7 Inches of Concrete
	[X Symbol]	8	9	[Dotted Symbol]	Loose Brown Poorly Graded Sand (SP) with Silt
	[X Symbol]	9	7		-Loose; Passing #200 Sieve @ 2'-4' is 7.5%
5	[X Symbol]	9	7		-Loose
10					
15					
20					

**COMMENTS:**

[Rock Core Symbol] Rock Core

[X Symbol] Split Spoon

## Hammond Street

APS Design and Testing, LLC